

# SEWING MACHINE THREADING GUIDE

## 1. UPPER THREADING

1. Place thread spool on the **spool pin**.
2. Pass thread through the **upper guide**.
3. Wrap thread around the **tension discs**.
4. Pull thread up through the **take-up lever**.
5. Pass through the **needle bar guide**.
6. Thread the **needle eye** (front to back).

*[Diagram: Upper Thread Path]*

## 2. BOBBIN SETUP

1. Wind thread onto the **bobbin** evenly.
2. Open the **bobbin case** cover.
3. Insert bobbin (ensure "P" shape rotation).
4. Slide thread through the **tension slot**.
5. Pull tail thread to the side.

*[Diagram: Bobbin Direction]*

## 3. THE FINAL STEP

Hold the upper thread tail. Turn the **handwheel** toward you one full rotation. Gently pull the upper thread to bring the bobbin thread loop through the needle plate.

**PRO TIP:** Always thread your machine with the **presser foot in the UP position** to ensure the thread seats properly within the tension discs.

Reference Chart - Beginner Basics Series