

THREADING REFERENCE CHART

Computerized Series Model 700-X

UPPER THREAD PATH

[Illustration: Thread Guide & Tension Discs]

Place spool on pin; secure with cap.

Pass thread through pre-tension guide.

Pull thread down through U-shaped channel.

Hook thread into Take-up Lever (Right to Left).

Feed behind needle bar thread guide.

BOBBIN SYSTEM

[Illustration: Drop-in Bobbin Direction]

Insert bobbin (thread should form a 'P' shape).

Guide thread into notch 'A'.

Draw thread along the path to blade 'B'.

Pull to trim excess thread.

Snap transparent cover back into place.

Maintenance Note: Always ensure the needle is at its highest position (using the Needle Up/Down button) before threading to prevent timing alignment errors.

© 2024 Sewing Systems Tech For Educational Reference Only