

# THREADING PATH GUIDE

Standard Digital Series

*[ Vector Illustration: Front View of Machine Path ]*

## **Spool Pin**

Place thread spool and secure with spool cap. Lead thread to the first guide.

## **Pre-Tension Guide**

Snap thread under the silver hook guide to ensure consistent feed.

## **Tension Disc Channel**

Bring thread down through the right channel and loop under the U-turn.

## **Take-up Lever**

Pull thread up and through the lever eye (ensure lever is at its highest position).

## **Needle Bar Guide**

Pass thread behind the horizontal guide located just above the needle.

## **Needle Eye**

Thread from front to back. Leave a 4-inch tail towards the rear.

**Maintenance Tip:** Always thread with the presser foot in the **UP** position to allow the tension discs to open and accept the thread correctly.