

MACHINE THREADING GUIDE

Standard Universal Setup

Spool Pin

Place thread spool and secure with spool cap.

Thread Guide

Pass thread through the upper rear guide loop.

Tension Disc

Lead thread down and around the tension channel.

Take-up Lever

Hook through the eyelet of the metal lever.

Needle Eye

Pass through lower guides and thread needle front-to-back.

REFERENCE CHART | ENSURE PRESSER FOOT IS UP WHILE THREADING