

# THREADING GUIDE: TOP LOADING BOBBIN

## UPPER THREAD PATH

### Upper Machine Diagram Placeholder

1. Place thread spool on pin and secure with cap.
2. Lead thread through the first thread guide.
3. Wrap around the tension discs (u-shaped path).
4. Bring thread up and through the take-up lever.
5. Pass thread down through the lower guides.
6. Thread the needle from front to back.
7. Pull 4-6 inches of thread through needle eye.

## LOWER BOBBIN INSERTION

### Bobbin Case Detail Placeholder

1. Remove transparent bobbin cover plate.
2. Insert bobbin (thread should form a "P" shape).
3. Guide thread into the first notch (6 o'clock).
4. Pull thread left into the tension spring.
5. Draw thread toward the back of the machine.
6. Replace the cover plate.

**Pro Tip:** Always turn the handwheel **toward you** (counter-clockwise) to pick up the bobbin thread before you begin sewing.